

# $3\frac{1}{2}$ - Digit LCR - Meter HM8018

Service-Manual







#### **KONFORMITÄTSERKLÄRUNG DECLARATION OF CONFORMITY DECLARATION DE CONFORMITE DECLARACIÓN DE CONFORMIDAD**

Hersteller / Manufacturer / Fabricant / Fabricante: HAMEG Instruments GmbH · Industriestraße 6 · D-63533 Mainhausen

Die HAMEG Instruments GmbH bescheinigt die Konformität für das Produkt The HAMEG Instruments GmbH herewith declares conformity of the product HAMEG Instruments GmbH déclare la conformite du produit HAMEG Instruments GmbH certifica la conformidad para el producto

Bezeichnung: LCR-Meter Product name: LCR meter Designation: LCR mètre Medidor de LCR Descripción:

Typ / Type / Type / Tipo: HM8018 HM8001-2 mit / with / avec / con:

Optionen / Options / Options / Opciónes:

mit den folgenden Bestimmungen / with applicable regulations / avec les directives suivantes / con las siguientes directivas:

EMV Richtlinie 89/336/EWG ergänzt durch 91/263/EWG, 92/31/EWG EMC Directive 89/336/EEC amended by 91/263/EWG, 92/31/EEC Directive EMC 89/336/CEE amendée par 91/263/EWG, 92/31/CEE Directiva EMC 89/336/CEE enmendada por 91/263/CEE, 92/31/CEE

Niederspannungsrichtlinie 73/23/EWG ergänzt durch 93/68/EWG Low-Voltage Equipment Directive 73/23/EEC amended by 93/68/EEC Directive des equipements basse tension 73/23/CEE amendée par 93/68/CEE Directiva de equipos de baja tensión 73/23/CEE enmendada por 93/68/EWG

Angewendete harmonisierte Normen / Harmonized standards applied / Normes harmonisées utilisées / Normas armonizadas utilizadas:

Sicherheit / Safety / Sécurité / Seguridad:

EN 61010-1: 1993 / IEC (CEI) 1010-1: 1990 A 1: 1992 / VDE 0411: 1994 Überspannungskategorie / Overvoltage category / Catégorie de surtension / Categoría de sobretensión: II

Verschmutzungsgrad / Degree of pollution / Degré de pollution / Nivel de

Elektromagnetische Verträglichkeit / Electromagnetic compatibility / Compatibilité électromagnétique / Compatibilidad electromagnética:

EN 61326-1/A1: Störaussendung / Radiation / Emission: Tabelle / table / tableau 4: Klasse / Class / Classe / classe B.

Störfestigkeit / Immunity / Imunitee / inmunidad: Tabelle / table / tableau / tabla A1.

EN 61000-3-2/A14: Oberschwingungsströme / Harmonic current emissions / Émissions de courant harmonique / emisión de corrientes armónicas: Klasse / Class / Classe / clase D.

EN 61000-3-3: Spannungsschwankungen u. Flicker / Voltage fluctuations and flicker / Fluctuations de tension et du flicker / fluctuaciones de tensión v flicker.

Datum / Date / Date / Fecha

22.07.2004 Unterschrift / Signature / Signatur / Signatura

> G. Hübenett **Product Manager**

#### General information regarding the CE marking

HAMEG instruments fulfill the regulations of the EMC directive. The conformity test made by HAMEG is based on the actual generic- and product standards. In cases where different limit values are applicable, HAMEG applies the severer standard. For emission the limits for residential, commercial and light industry are applied. Regarding the immunity (susceptibility) the limits for industrial environment have been used.

The measuring- and data lines of the instrument have much influence on emmission and immunity and therefore on meeting the acceptance limits. For different applications the lines and/or cables used may be different. For measurement operation the following hints and conditions regarding emission and immunity should be observed:

#### 1. Data cables

For the connection between instruments resp. their interfaces and external devices, (computer, printer etc.) sufficiently screened cables must be used. Without a special instruction in the manual for a reduced cable length, the maximum cable length of a dataline must be less than 3 meters and not be used outside buildings. If an interface has several connectors only one connector must have a connection to a cable. Basically interconnections must have a double screening. For IEEE-bus purposes the double screened cables HZ72S and HZ72L from HAMEG are suitable.

#### 2. Signal cables

Basically test leads for signal interconnection between test point and instrument should be as short as possible. Without instruction in the manual for a shorter length, signal lines must be less than 3 meters and not be used outside buildings.

Signal lines must screened (coaxial cable - RG58/U). A proper ground connection is required. In combination with signal generators double screened cables (RG223/U, RG214/U) must be used.

#### 3. Influence on measuring instruments.

Under the presence of strong high frequency electric or magnetic fields, even with careful setup of the measuring equipment an influence of such signals is unavoidable.

This will not cause damage or put the instrument out of operation. Small deviations of the measuring value (reading) exceeding the instruments specifications may result from such conditions in individual cases.

HAMEG Instruments GmbH

Declaration of Conformity	2
General information regarding the CE-marking	2
3½-Digit LCR-Meter HM8018	4
Specifications	5
Alignment procedure	6
Circuit and layout diagrams	7

# $3\frac{1}{2}$ - Digit LC Meter HM8018



Option H0801



Mainframe HM8001-2



Option HZ18 Kelvin test lead



Measurement functions: L, C, R

3%-digit display with 2,000 counts, basic accuracy 0.5 %

4-wire measurement

Max. resolution:  $0.1\,pF$ ,  $0.1\,\mu H$ ,  $10\,m\Omega$ ,  $0.01\,\mu S$ 

Internal bias for electrolytic capacitors selectable

Offset adjustment of cable capacity for the "Kelvin test lead"

AC voltage signal at rear-panel BNC connector proportional to value shown in the display (with Option H0801 only)

Mainframe HM8001-2 required for operation

#### 3½-Digit LC Meter HM8018

Valid at 23 °C after a 30 minute warm-up period

#### Operating modes

C measurement L measurement

Series inductance L, Shunt capacitance C Series resistance R, Parallel conductance G

#### Measurement ranges

L: 200 µH-200 H (7 ranges) Rs:  $20 \Omega$ - $200 k\Omega$  (5 ranges) C: 200 pF-200 µF (7 ranges) G: 20 µS-200 mS (5 ranges)

Max. resolution: 0.1 pF

 $0.1 \, \mu H$ 0.01 Ω  $0.01\,\mu S$ 

Measurement frequencies:

(sine wave signal) ~160 Hz, 1.6 kHz, 16 kHz  $[\omega = 10^3, 10^4, 10^5 \text{ s}^{-1}]$ 

max. 1 V<sub>pp</sub> max. 36 mA (eff.) Measurement voltage: Measurement current:

Power output to device under test:

max. 3.2 mW ± [0.5% of reading Measurement accuracy:

 $+(3 \text{ digit s} + 0.5 \text{ pF}/0.5 \mu\text{H}/10 \text{ m}\Omega/0.01 \mu\text{S})]$ 

Measurement error resulting from separation of the real and imaginary part ≤1% at tanφ≥1

## Display Sampling rate:

Type of measurement:

31/2-digit 7-segment LED display 2 measurements per second 2- or 4-wire measurement

#### Miscellaneous

Inputs are short-circuit-proof and overvoltage protected up to 100 V with a maximum energy consumption of 10 mJ (Δ capacitor 2 μF, charged to

#### Polarization voltage for C measurement: 2V

Zero point correction for display

Compensation of probe capacitance (HZ18)

AC voltage signal at rear-panel BNC connector proportional to value shown in the display (HM8001 with option H0801)

+5 V/200 mA Power supply (from mainframe): -13 V/130 mA

+13 V/130 mA  $(\sum = 4.5 \text{ W})$ 

Operating temperature: + 10° C to + 40° C

80 % (without condensation) Max. relative humidity: Dimensions (W x H x D) (without 22-pole flat plug): 135 x 68 x 228 mm

Weight: approx. 0.65 kg

Accessories supplied: Operator's Manual Optional accessories: HZ18 Kelvin test lead

# www.hameg.com

#### Alignment procedure HM8018

#### Measuring equipment required:

- Oscilloscope 20 MHz (e.g. HM303)
- Frequency counter (e.g. HM8021)
- Digital Multimeter DMM (e.g. HM8012)
- Load 100 kΩ 0.1%,
- Load 1kΩ 0.1%
- Capacitor 470 pF (PP or Polysulfon)
- Capacitor with known value between 10...16 nF 0.1%

#### Presettings:

To start the calibration, first adjust the R-trimmer "Probe comp." and "Display Zero" at the front panel to center position. Disconnect all cables of the frontpanel HM8018.

#### 1. Test of oscillator frequency:

Connect frequency counter (TI measuring) to testpoint "Synchro". Set LC-Meter to range 2 pF, "G". Adjust period to 6280 ps ±25 ps with R111.

#### 2. Adjustment of measuring frequency:

Set LC-Meter to the ranges described below. Adjust period time as following:

2 µF VR103 (3) 6283 µs ±1 µs 200 nF VR102 (2) 628.3 µs ±1 µs 200 pF VR101 (1) 62.83 µs ±1 µs

#### 3. Adjust offset (PD):


Connect oscilloscope (AC-coupling, max. sensitivity) to TP5 and set LC-Meter to range 200 nF, "G". Adjust amplitude to minimum with VR106 (6).

#### 4. Adjust offset (Uref):

Connect DMM (VDC)to TP5. Set LC-Meter to 200 mH. Adjust VR109 (9) to  $0 \pm 1$  mV.

#### 5. Symmetry:

Set LC-Meter to 200nF, "G". Connect resistance  $100 \, k\Omega$  to the banana jacks and the oscilloscope (AC,  $10 \, mV/Div.$ , 0,1 ms/Div.) to TP7. Adjust VR108 (8) for same amplitude.



#### 6. Adjust offset (Vin):

Disconnect all cables from the instrument. Set LC-Meter to range 200 nF. "G". Connect DMM (VDC) to TP7. Adjust VR110(10) to  $0 \pm 1$  mV.

#### 7. Range selection und gain:

Connect resistance 1 k $\Omega$  to the banana jacks. Set LC-Meter to 200 mH. Repeat the following steps several times.

- a) Set range to "Rs". Adjust the display of LC-Meter to 1000 ±1 Digit by means of VR105 (5).
- b) Set range to "G". Adjust the display of LC-Meter to 1000 ±1 Digit by means of VR401 (21).

#### 8. Adjustment of input capacitance:

Connect capacitor 470 pF to banana jacks. Set LC-Meter to 200 pF, "G". To adjust the input capacitance, it is necessary to close the module housing (a. and b.).


- a) Connect oscilloscope (AC-coupling) to TP5, with modul cover closed. Pass the cable through holes in the module cover. Reduce amplitude to minimum by means of VR107 (7).
- b) Connect oscilloscope to TP4 [same way as a)]. Remove capacitor 470 pF. Reduce amplitude to minimum by means of VR111 (11).

#### 9. Range selection "C", "L":

Remove all cables from HM8018. Set LC-Meter to 200 pF, "C". Adjust "Display Zero" (front panel) to  $0\pm3$  digit on the display of HM8018.

- a) Connect Kelvin probe HZ18 to Kelvin input (5-pin diode jack) and reduce the reading to 0  $\pm$ 3 digit via "Probe comp." on front panel.
- b) Disconnect HZ18 and connect a known capacitor between 10 nF and 16 nF to the banana jacks. Set LC-Meter range to 20 nF, "C". Adjust VR104 (4) for same reading as value of the capacitor.


## Mainboard HM8018



Steckerleiste, Versorgungsspannungen Multipoint connector, supply voltages Carte connecteur, tensions d'alimentation Placa connector de los voltajes de alimentacion


#### R501, R502

Programmwiderstände **Programming Resistors** Résistances de programmation Resistencia segun programa




Bestückungsplan, Digitalanzeige Implantation des composants, Affichage numerique

### Component Locations, Digital Display Localizacion de componentes, Indicador digital



Bestückungsplan, Eingangsverstärker Implantation des composants, Amplificateur d'entrée

**Component Locations, Input Amplifier** Localizacion de componentes, Amplificador de entrada





1 N 4 1 4 9 - -FDH300 -K-


HM8018 T 89 06 18


Component Locations, Main Board Localizacion de componentes, Placa base


Bestückungsplan, Grundplatte Implantation de composants, Circuit principal













Oscilloscopes



Spectrum Analyzer



**Power Supplies** 




Modular System 8000 Series



Programmable Instruments 8100 Series







# www.hameg.de

Subject to change without notice 4S-8018-00E0 / 10-01-2006-gw © HAMEG Instruments GmbH A Rohde & Schwarz Company ® registered trademark

DQS-Certification: DIN EN ISO 9001:2000 Reg.-Nr.: 071040 QM HAMEG Instruments GmbH Industriestraße 6 D-63533 Mainhausen Tel +49 (0) 61 82 800-0 Fax +49 (0) 61 82 800-100 sales@hameg.de